



Application Guide BLOCKSIL N S



Surface Preparation:

Brush off all dust and debris, remove any oil and grease with xylene.
Surface should be dry with no frost.

Application:

Apply using flat filler trowel, Brush & Roller.
Application temperature 5 - 35°C.

Method:

Mix Product before application.
Apply by forcing product into the crack until flush with surface.

Note:

Can be used in conjunction with Blocksil HD, Blocksil SF20 & Blocksil ONE.

Exposure controls / personal protection

Avoid contact with eyes and skin. Do not eat, drink or smoke during work. Remove contaminated, saturated clothing immediately. Wash hands before break and after work.

Hand Protection:	Gloves
Eye Protection:	Safety goggles.
Skin Protection:	Light protective clothing.

Always refer to Safety Data Sheet before use